

EPISODE 56 Online O&M dispersion analysis

Bankable. Reliable. Local.

Online O&M dispersion analysis

>> Background

PV plants are an incredible asset with long-term income. Their construction is quick, but the time required for operation and maintenance is more than 25 years. Compared with small PV plants, the number and scale of large PV plant components are very big, and late 0&M and troubleshooting is increasingly difficult. There can also be an accumulation of problems with equipment selection, construction guality, etc. in the early stage. These factors will affect the revenue of power generation in the later stage of power plant operation. This Solis workshop will focus on how to use digital tools to assist daily operations.



What is dispersion analysis?

PV string dispersion analysis is mainly used to evaluate the consistency of PV string power generation and its performance. In practical applications, it reflects the current situation of each DC branch of the inverter. When the current dispersion rate is low, it indicates that the power generation performance of each branch is consistent. If the current dispersion rate is high, it indicates that the branch current deviation is big, meaning the next stage of fixed-point investigation can be carried out.

The formula for calculating the current dispersion of PV string is as follows:

Dispersion = standard deviation of PV string current/mean value of PV string current *100%

In the PV plant information management platform, the separate rate of PV string current adopts the weighted average of the discretization rate at each moment of the day to evaluate the discretization rate of the whole day. For evaluation of the PV string current dispersion value, it is generally divided into the following five cases:

Analysis Discrete Rate of Inverter String



Range of current disper	rsion Relevant description
(0~5% The PV string current r
5%-	~10% The running current of
10%-	~20% Some PV string curren
	>20% The running current of disconnected), which a
Off	f-line Some PV strings corre

Scene application

Discrete rate analysis can be mainly used as a helpful tool to troubleshoot power and current attenuation caused by shadow blockage of PV systems, dirty PV panels, mixed PV panel installations, PV panel damage, etc. The discrete rate analysis of the PV system can be performed in the operation and maintenance center of SolisCloud:



ž	solis		ALL.	solis					🖾 Large S	creen 💬 MSG	🕑 Help		Ŧ
		А										Expe	rt
₽	Overview	My		0&M	Alarm In	formation 🛓	on :	Min Capacity h	- Max Capacity	h Select Time :	E Start Time -	End Time	
8	0&M	Plar	æ	Alarm Information			rch	Reset					
131		G	-		My Favorites :	Select favorites 🗸 🗸	S	Resolution	Alarm Duration	Start Time	Recovery Time	Operation	
٩		Ti		IV Curve Diagnosis	Disatellarea	E. L. L. L. L.	la la	1. If it occurs by Am	<1h	2023-04-21 16:16 (Operation	
88			1.4		Plant Name :	Enter plant name	If.	1. If it proves by a	c1h	2023-04-21 12-16 (-	Oneration	
8		-	LÃI.	Dispersion Rate Ana	Grade	Status		1. If it accurs by an	eth	2022-04-21 1545 (Operation	
ß	Intelligent O&M		٢	,	Giude	Sutus		1. If it around by a	45	2023-04-21 10110 (Operation	
					Tip	Pending		1. If it occurs by a	<1n	2023-04-21 10:10 (Operation	
		Tip	88					1. If it occurs by a	<1h	2023-04-21 12:16 (Operation	
		Ti	_			Pending		1. If it occurs by a	<1h	2023-04-21 08:16 (Operation	
		Tip	번			Pending		1. If it occurs by a	<1h	2023-04-21 09:16 (Operation	
		Tip	16 53 19			renaing		1. If it occurs by a	<1h	2023-04-21 16:16 (Operation	
		Tip				Pending		1. If it occurs by a	<1h	2023-04-21 16:16 (Operation	
		Tij						1. If it occurs by a	<1h	2023-04-21 09:16 (Operation	
					Tip	Pending	4	5 6 10	000 > Go to 1				
						Pending							

In addition, when using the application tool you need to pay attention to the following problems:

- 1. It is suggested to exclude abnormal weather scenarios such as cloudy and rainy days when conducting a dispersion analysis.
- 2. Each inverter connects to more than six PV strings.
- 3. The operation viewing time is from 10:00 am to 2:00 pm every day, so you can check the day's data after 10:00 am.
- 4. For branches that are not connected to the PV string, deselect them before performing analysis to avoid interference.



Shadow occlusion: In the following power station case, there are a total of 9 inverters. Through analysis, the discretization rate of a PV string connected to two inverters is between 10% and 20%. The PV13string and PV7string currents are low, so field investigation is required to determine the cause.



From field investigation it can be seen that the PV string corresponding to the two inverters with high discretization rates has an object blocking them, which leads to the electrical and distribution losses caused by shade at certain times of the day. The shadow occlusion results in a gap between the running current and the current value of the normal PV string and the corresponding increase in the discretization rate. For this kind of occlusion, the customer needs to migrate and transform the PV panel to a more open area.



PV panel defects: In the same power station case, except for one offline inverter, the discretization rate is 6% for the 8 online inverters and 20% for the connected components. Moreover, the multi-day analysis of the power station was continuously checked and was consistently more than 20%. The corresponding string current of the inverter was confirmed to be low.

12	离散率分析														
													7		
													/		
	2														
							0								
11	0—20% 5路明显编任					-5 个别	-10% 支勤情任					0- 1	- 5% 王智		
		-	-								-				旗作
	PV10	PV11	PV12	PV13	PV14	PV15	PV16	PV17	PV18	PV19	PV20	PV1	PV2	PV2	
	7.3	68	7	25	6.7	65	67	7.4	7	4.5	7.2				R
	6.9	6.9	6.4	6	6	64	6.2	63	62	6.5	6.5				82
	7.5	7.3	7	7.4	6.6	7.1	7	67	7	67	67				12. 11
	7.2	7.4	7.6	7.3	7.6	7	7.4	67	7.6	7.5	7.5				R
	7.8	7.5	77	7.4	7	69	7.4	7.1	68	7.5	7				121
	7.1	7.2	7.1	7.1	7.3	67	68	6.9	6.5	67	63				82
	7	6.5	6.8	7.2	7.1	6.5	7.3	61	7.2	6.6	6.5				17. 1
	7.4	7.2	7.2	7.4	7.4	7.2	7.3	7.7	67	7.3	7.1				12
	7.5	7.5	7.7	7.4	7.7	7.5	7.9	7.4	7.4	7.5	7.4				12.00

5

										进合路线水	奏改率分析		
8				8									
6				8									
4 -			4										
2	1		1	2	1		1			0			
0 -	高线 存在通讯故障	个加	20%以上 支旗存在故障		海线 存在通讯故障	2 个部5	0%以上 E飾存在故籍			10 个相互	1~20% 期利型傳紙		
共9台设备				共9台设备									
递支器名称	逆变器SN	高散率(%)	PV电流(A) PV1 F	递去署名称	举念器 SN	高版牢(%)	PVilte:(A) PV1	PV2	PV3	PV4	PV5	PV6	
2.80∰ 9483321		35.1	19.3 1	送完發 9曲0321		35.05	21	21	13.8	64			
送史冊 9441332	3	6.18	65 2	送完發 9春1332	.2	9.35	69	22.2	21.1	14			
逆攻勝 9年 3330		1.12	22 2	逆虫器 9車 3330		1.37	21.6	21.6	22.2				
边现县 940333	2	0.87	0.1 2	送來器 9曲 0333		1		223	22.8	22.7			
逆攻骨 940 3330 (過音光滑748)	(manual 10)	0.57	17.1 1	汽运器 240333	2	0.89		22.6	22.6	21.8			
逆炮器 940 0333		0.54	01 2	逆攻器 9曲 3330(1100000000		0.79	188	19	19.2				
<u>例成時</u> 9480333	3	0.11	0.1 2	送水桥 9曲0333		0.55		22.7	22.6	22.3			
逆蛇骨 9403330		0	23.7 2	逆攻静 9曲3330		0.22	22.4	22.4	22.3				
送史册6曲22211	;			送宽静0串22211		10 C							

There are no occlusions in this scene, so it can be inferred that there may be some problems with a PV panel. Further investigation and analysis of the PV panel are needed to exclude whether the PV panel surface is dirty or if there are other causes of power and current attenuation before determining the fault.

Conclusion:

>>> Long-term reliable operation of the power station cannot be the traditional on-site checks are time-consuming and laborious. If analysis tool is easy to operate and accessible for power plant personnel in terms of daily maintenance and troubleshooting.

separated from the usual operation and maintenance checks. Since the power station is large, the problems are diverse and complex, and various online analysis tools can be used to assist with O&M, you can get more accurate results with less effort. The power plant dispersion

w: solisinverters.com	Search for 'Solis'	